Repair Item By Location

Walls Group, Inc.

-	oplicant De Johnson				<u>Number</u> ohnson
	pplicant's A		Property Address		
	9 N Sample nyTown, US		709 N Sample Ave. AnyTown, US 55555		
File Nu	mber J Joł	inson			
lst F	loor				
Qty	Repair Item				Item Tota
6	Bi-Fold Do	oor(s) 2' to 3' v	wide (as selected by owner))	\$1,860.0
	Details:	bedroom closets	supply and install new bi-fold doors where missing. Doors shall be instant astallation guidelines with all hardwa	alled per the MFG	
1250	Vinyl Plan	k Flooring			\$7,625.0
	Details:		all new plank style vinyl flooring thro an allowance of \$3.50 sq/ft.	oughout both units as selected	
				Sum Total:	\$9,485.00
				% of Renovation/Rehab:	5.95 %
Attic					
Qty	Repair Item				Item Tot:
1350	-	dional Insulati	ion at Attic		\$4,185.0
	Details:	existing insulation	additional insulation at all attic areas on to provide a completed upgrade o ilding code requirements.		
				Sum Total:	\$4,185.00
				% of Renovation/Rehab:	2.63 %
Base	ement				
Qty	Repair Item				Item Tota
435	Allowance	e for Baseboa	rds & Base Shoe		\$2,392.5
	Details:	Primed MDF bas	HOE ALLOWANCE: Contractor sha seboard and shoe throughout at 1st finished flooring (materials allowand	floor, 2nd floor and basement	
625	Basement	Wall Insulation	on R-11 Batt Contained In B	Bag Draped	\$1,468.7
	Details:	exposed as part	all R-11 Craft Faced Batt insulation of the mold remediation and water of Note: Other areas if required by the	damage restorations at the	
300	Ceramic F	loor Tile			\$4,950.0
	Details:	tile at all exterior to infill where bas tile system. Tiles	mic tile to reasonably match and ble r walls to the closest grout lines with sement floor is cut to accommodate s to be used are to be of similar size dard colors and sizes.	an average of approx. 2' wide the installation of a new drain	
					¢10 775 (
145	Drain Tile	System with \$	Sump Pump, etc.		\$13,775.0

Details: Furnish and install drywall and accessory pieces (USG or equal) at basement removed due to flood damages, and all other renovations, etc. NOTE: Purple drywall board (moisture-, mold- and mildew-resistant) at the bottom 48" of all walls throughout the basement, standard drywall all other areas. All areas with paneling now to be drywall. all Mid-Grade Basement Escape Window with Metal Window Well Details: Provide all materials and labor to excavate and install new egress window with metal egress size window well frame with ladder. all new gas water heater Details: Details: Provided install new 50 gallon water heater all piping connections, electrical requirements, etc. as necessary for a full installation. all new Pre-Hung doors with casing & lockset Details: Details: Provide and install new mid-grade hollow core panel style interior doors with new door casings, locks and misc. hardware as required as replacements for doors removed during basement renovations / restorations. t interior walls, ceilings, doors, and trims, etc. Details: Provide Painting at basement and other areas affected by renovations. Painting to	\$3,950.00 \$2,400.00 \$3,600.00 \$6,300.00
Details: Provide all materials and labor to excavate and install new egress window with metal egress size window well frame with ladder. all new gas water heater Details: Provided install new 50 gallon water heater all piping connections, electrical requirements, etc. as necessary for a full installation. all new Pre-Hung doors with casing & lockset Details: Provide and install new mid-grade hollow core panel style interior doors with new door casings, locks and misc. hardware as required as replacements for doors removed during basement renovations / restorations. t interior walls, ceilings, doors, and trims, etc.	\$2,400.00
metal egress size window well frame with ladder. all new gas water heater Details: Provided install new 50 gallon water heater all piping connections, electrical requirements, etc. as necessary for a full installation. all new Pre-Hung doors with casing & lockset Details: Provide and install new mid-grade hollow core panel style interior doors with new door casings, locks and misc. hardware as required as replacements for doors removed during basement renovations / restorations. t interior walls, ceilings, doors, and trims, etc.	\$3,600.0
Details: Provided install new 50 gallon water heater all piping connections, electrical requirements, etc. as necessary for a full installation. all new Pre-Hung doors with casing & lockset Details: Provide and install new mid-grade hollow core panel style interior doors with new door casings, locks and misc. hardware as required as replacements for doors removed during basement renovations / restorations. t interior walls, ceilings, doors, and trims, etc.	\$3,600.00
requirements, etc. as necessary for a full installation. all new Pre-Hung doors with casing & lockset Details: Provide and install new mid-grade hollow core panel style interior doors with new door casings, locks and misc. hardware as required as replacements for doors removed during basement renovations / restorations. t interior walls, ceilings, doors, and trims, etc.	
Details: Provide and install new mid-grade hollow core panel style interior doors with new door casings, locks and misc. hardware as required as replacements for doors removed during basement renovations / restorations.	
door casings, locks and misc. hardware as required as replacements for doors removed during basement renovations / restorations. t interior walls, ceilings, doors, and trims, etc.	\$6,300.0
	\$6,300.0
-	
include but not be limited to interior walls, ceilings, doors, trims. and associated surfaces typically painted etc. with 1 coat of primer and 2 coats paint.	
ove & Replace Bathtub	\$600.00
Details: Remove and reset existing bathtub at basement bathroom to allow for mold and water damages and the installation of a new drain tile system. Note: Ceramic tile repairs / replacements are listed separately in this SOR / BOR.	
air Walls & Framing	\$7,500.0
Details: Allowance for all wall framing and ceiling soffit framing repairs as necessary following selective demolition at basement areas to ready for drywall installations condition. It is assumed that there will be approximately 120 LF of wall and 400 SF of soffit required.	
ctive Demolition	\$8,000.0
Details: Provide all Selective Demolition in conjunction with mold remediation, cleaning & sanitation throughout Basement with removal of finishes, drywall, ceramic tile, paneling trims etc. at interior walls, etc. to 48" above the basement floor. By a certified EPA mold remediation contractor.	
	\$61,781.2
Sum Total:	38.78 %
% of Renovation/Rehab:	14 m ·
% of Renovation/Rehab:	Item Tota \$1,050.00
% of Renovation/Rehab:	

Sum Total:	\$1,050.00
% of Renovation/Rehab:	0.66 %

Exte	erior		
Qty	Repair Item		Item Tota
1	Caulking	General Exterior	\$550.00
	Details:	Provide caulking (sealant) installation at all openings, cracks or joints at the exterior of the building to reduce air infiltration and water leaks.	
650	Paver Pat	o and Walkway, Repairs / Replacement	\$4,550.00
	Details:	Provide professional removal and resetting of masonry patio pavers to restore the patio to a good, stable, and aesthetically pleasing condition at the left and right side walks and rear patio of the home to provide proper water shed away from the home.	
		Sum Total:	\$5,100.00
		% of Renovation/Rehab:	3.20 %
Exte	erior Wall	6	
Qty	Repair Item		Item Tota
600	Spot Rep	int Exterior Masonry - All Areas Where Necessary	\$6,900.0
	Details:	Repoint and/or repair masonry brick and stonework in all areas around the home as necessary, addressing step cracking and deteriorated or washed-out mortar joints.	
		Sum Total:	\$6,900.00
		% of Renovation/Rehab:	4.33 %
=en	ces & Ga	es	
Qty	Repair Item		Item Tota
1	Allowance	for Fence Repairs and Replacements	\$1,900.0
	Details:	Allowance to remove existing rotting / damaged fencing wood and replace with new. Work shall also include gate repairs, straightening and securing significantly leaning fence posts and other deficiencies.	
		Sum Total:	\$1,900.00
		% of Renovation/Rehab:	1.19 %
Fror	nt Entry S	tairs	
Qty	Repair Item		Item Tota
1	Repair Ex	terior Stairs	\$1,050.00
	· ·	Provide repairs and replacement of front entry stairway tiles that have been overlayed on the concrete stairs to restore them to good, safe and serviceable condition.	
		0 T	¢4 050 00
		Sum Total:	\$1,050.00

		. ,
%	of Renovation/Rehab:	0.66 %

Qty	Repair Item		Item Total
1	Allowance	- General Electrical Repairs	\$8,000.00
	Details:	Allowance for Contractor to revise / upgrade and provide all corrections to electrical work at all areas required to meet current building code requirements as listed below:	
1	Allowance	e for New 2 Car Garage	\$16,500.0
	Details:	See Architectural Drawings	
5	Cleaning-	General Requirement	\$2,750.00
	Details:	Provide general daily clean up of project during construction and removal of debris with dumpster(s) and/ or required hauling for legal disposal of general daily clean up related debris only.	
0	GENERAL	CONDTIONS TO BE INCLUDED IN THE COSTS OF WORK ITEMS	\$0.00
	Details:	THE FOLLOWING GENERAL CONDITIONS ARE TO BE INCLUDED AT NO ADDITIONAL COSTS AND REVIEWED CAREFULLY AS IT APPLIES TO ALL WORK AS LISTED ABOVE IN ALL SECTIONS OF THIS SOR / BOR:	
1	Vanitv 24'	with Solid Surface Top, Sink and Faucet Set	\$13,775.0
	Details:	Remove and replace damaged vanity and /or sink, etc. with new vanity with solid surface top, new faucet and drain set, new supply lines and new P-Trap and associated drain piping. All work to be preformed by qualified contractor.	
		Sum Total:	\$41,025.00
		% of Renovation/Rehab:	25.75 %
lall	Bath		
Qty	Repair Item		Item Tota
80	Ceramic T	ile at Shower Walls and Tub Surround(s)	\$1,920.00
	Details:	Provide and Install ceramic tile to walls of tub and shower surrounds at bathroom(s), with tile as selected by owner from standard styles and colors. Note: Materials based on an allowance of \$5.50 SF for tile materials.	
		Sum Total:	\$1,920.00
		% of Renovation/Rehab:	1.21 %
ntei	rior		
Qty	Repair Item		Item Tota
500	Allowance	e - Drywall Repairs	\$2,250.00
	Details:	Remove and replace drywall / plaster ceilings at areas in bedroom(s) and kitchen at any areas of new construction and where significant water damage has occurred to the extent to eliminate any possible mold at the attic areas and insulation in those areas. NOTE: Bathroom walls are to be drywall finishes with ceramic tile only at bathtub surround.	
			\$2,250.00
	. <u>.</u> .	% of Renovation/Rehab:	1.41 %
Righ	nt side of	building	
Qty	Repair Item		Item Tota
1		Paver Stairs / Steps	\$4,750.00
	D / 1		
	Details:	Allowance to remove existing masonry paver stairs that are loose, damaged and deteriorated and replace with new masonry paver in style and color as selected from standard sizes and colors by owner.	
		deteriorated and replace with new masonry paver in style and color as selected from standard sizes and colors by owner.	\$4,750.00

	Sum 100mi	+ -,
%	of Renovation/Rehab:	2.98 %

	f - Gener	ai	
Qty	Repair Item		Item Total
25	Remove &	& replace roof with 30 year shingles	\$15,875.00
	Details:	Remove all roofing systems and replace at house and garage with with Architectural grade shingles 30 year minimum warranty shingles in color as selected by owner.	
		Sum Total:	\$15,875.00
		% of Renovation/Rehab:	9.96 %
Stai	rs - Interi	or	
Qty	Repair Item		Item Total
15	Install pro	oper Handrails & Railings	\$375.00
	Details:	Allowance for Installation of proper handrails and railings at open sides of stairs at main level to lower level to meet current building codes.	
		Sum Total:	\$375.00
		% of Renovation/Rehab:	0.24 %
			0.24 %
Thro _{Qty}	Dughout I Repair Item		Item Total
_	Repair Item		
Qty	Repair Item	Home	Item Total
Qty	Repair Item Smoke &	CO Detectors (Hardwired / Bluetooth) Install new Smoke and Carbon Monoxide (CO) Alarm Detectors throughout Building to replace missing, damaged and older detectors to meet current code	Item Total
Qty	Repair Item Smoke &	CO Detectors (Hardwired / Bluetooth) Install new Smoke and Carbon Monoxide (CO) Alarm Detectors throughout Building to replace missing, damaged and older detectors to meet current code requirements (hardwired / bluetooth detectors type are assumed to be required).	Item Total \$1,350.00
Qty 9	Repair Item Smoke &	Home CO Detectors (Hardwired / Bluetooth) Install new Smoke and Carbon Monoxide (CO) Alarm Detectors throughout Building to replace missing, damaged and older detectors to meet current code requirements (hardwired / bluetooth detectors type are assumed to be required). Sum Total:	Item Total \$1,350.00 \$1,350.00
Qty 9	Repair Item Smoke & Details:	Home CO Detectors (Hardwired / Bluetooth) Install new Smoke and Carbon Monoxide (CO) Alarm Detectors throughout Building to replace missing, damaged and older detectors to meet current code requirements (hardwired / bluetooth detectors type are assumed to be required). Sum Total:	Item Total \$1,350.00 \$1,350.00
Qty 9	Repair Item Smoke & Details:	Home CO Detectors (Hardwired / Bluetooth) Install new Smoke and Carbon Monoxide (CO) Alarm Detectors throughout Building to replace missing, damaged and older detectors to meet current code requirements (hardwired / bluetooth detectors type are assumed to be required). Sum Total:	Item Total \$1,350.00 \$1,350.00 0.85 %
Qty 9 Wine Qty	Repair Item Smoke & Details:	CO Detectors (Hardwired / Bluetooth) Install new Smoke and Carbon Monoxide (CO) Alarm Detectors throughout Building to replace missing, damaged and older detectors to meet current code requirements (hardwired / bluetooth detectors type are assumed to be required). Sum Total: % of Renovation/Rehab:	Item Total \$1,350.00 \$1,350.00 0.85 % Item Total
Qty 9 Wine Qty	Repair Item Smoke & Details: dows Repair Item Repair Wi	CO Detectors (Hardwired / Bluetooth) Install new Smoke and Carbon Monoxide (CO) Alarm Detectors throughout Building to replace missing, damaged and older detectors to meet current code requirements (hardwired / bluetooth detectors type are assumed to be required). Sum Total: % of Renovation/Rehab: Indow(s) - General Repairs Provide general repairs and replacements (as necessary) at 2 windows including to include glass & glazing replacements at (1) window, and locking hardware repairs or replacement at (1) window to restore windows to good and serviceable condition.	Item Total \$1,350.00 \$1,350.00 0.85 % Item Total \$325.00
Qty 9 Wind Qty	Repair Item Smoke & Details: dows Repair Item Repair Wi	CO Detectors (Hardwired / Bluetooth) Install new Smoke and Carbon Monoxide (CO) Alarm Detectors throughout Building to replace missing, damaged and older detectors to meet current code requirements (hardwired / bluetooth detectors type are assumed to be required). Sum Total: % of Renovation/Rehab: mdow(s) - General Repairs Provide general repairs and replacements (as necessary) at 2 windows including to include glass & glazing replacements at (1) window, and locking hardware repairs	Item Tot \$1,350.0 \$1,350.0 0.85 % Item Tot

Grand Total \$159,321.25